## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

## **BUNDESREPUBLIK DEUTSCHLAND**



**1** 

(11)

2

Deutsche Kl.: 37 a, 1/04

Offenlegungsschrift 2354316

Aktenzeichen:

P 23 54 316.0

Anmeldetag:

30. Oktober 1973

Anmeldetag:

9. Mai 1974

Ausstellungspriorität:

30 Unionspriorität

② Datum:

1. November 1972

33 Land:

V. St. v. Amerika

3) Aktenzeichen:

302678

Bezeichnung:

Bauverfahren und Einrichtung zu seiner Durchführung

61

Zusatz zu:

**@** 

Ausscheidung aus:

1

Anmelder:

Forest City Dillon, Inc., Akron, Ohio (V.St.A.)

Vertreter gem. §16PatG:

Bahr, R.H., Dipl.-Ing.; Betzler, E., Dipl.-Phys.;

Herrmann-Trentepohl, W., Dipl.-Ing.; Pat.-Anwälte, 4690 Herne u.

8000 München

@

Als Erfinder benannt:

Dillon, Thomas Joseph, Akron, Ohio (V.St.A.)

ORIGINAL INSPECTÉD



